MATERIAL SAFETY DATA SHEET

PRODUCT NAME: Roberts 2057 Premium Vinyl Composition Tile Adhesive Roberts MSDS Code # 2057C PRODUCT USES: For installing vinyl composition floor tile

SECTION 1 - MANUFACTURER IDENTIFICATION MANUFACTURER'S NAME: ROBERTS COMPANY CANADA LTD. ADDRESS: 2070 Steeles Ave. Bramalea, Ontario L6T 1A7 24 HOUR (CANUTEC) PHONE: (613) 996-6666 DATE REVISED: 03/01/04

W.H.M.I.S. CLASSIFICATION: NON-CONTOLLED

V.O.C. CONTENT: 0 Calculated

NAME OF PREPARER: Peter Sharko INFORMATION PHONE: (905) 791-4444 SOURCES USED: Raw material supplier M.S.D.S., US M.S.D.S.

INGESTION X

COTION 8 - LINTADDOLIC INCORDIENTS INCODMATION

SECTION II • HAZARDOUS INGREDIENTS INFORMATION						
COMPONENT	APPROX. %	UN#	CAS#	LD50	LC50	
NO REPORTABLE						
INGREDIENTS						

SECTION III - PHYSICAL DATA SPECIFIC GRAVITY (H20=1): 1.0 pH: 9.0 - 9.6 BOILING POINT: 100° CFREEZING POINT: N/A EVAPORATION RATE (BUTYL ACETATE=1): Slower VAPOUR DENSITY (AIR=1): Heavier than air EVAPORATION RATE (ETHYL ACETATE=1): Slower VAPOUR PRESSURE (MM OF MERCURY): N/A SOLUBILITY IN WATER: PERCENT VOLATILE: 45 Miscible ODOUR THRESHOLD (PPM): Not available APPEARANCE AND ODOUR: Beige, thin paste, slight odour. SECTION IV - FIRE AND EXPLOSION DATA FLASHPOINT (specify method): N/A METHOD USED: P.M.C.C. IMPACT SENSITIVITY: Insensitive FLAMMABLE LIMITS (% BY VOLUME): LOWER: N/A UPPER: N/A SENSITIVITY TO STATIC DISCHARGE: Insensitive FIRE EXTINGUISHING MEDIA: Foam, CO2, Dry Chemical AUTO IGNITION TEMP: N/A TDG FLAMMABILITY CLASSIFICATION: Not regulated. SPECIAL FIRE-FIGHTING PROCEDURES: Poses minimal fire hazard. Self-contained breathing apparatus should be worn for fires involving this product. UNUSUAL FIRE AND EXPLOSION HAZARDS: Containers may explode if exposed to extreme heat, isolate from heat, electrical equipment sparks and open flames. Do not put in contact with oxidizing materials.

SECTION V - REACTIVITY DATA

1

I

STABILITY: Stable INCOMPATIBILITY (Materials to avoid): Strong oxidizers and caustics HAZARDOUS DECOMPOSITION PRODUCTS: CO, CO2, and Hydrocarbons upon combustion, HAZARDOUS POLYMERIZATION: Will not occur

CONDITIONS TO AVOID; Excessive Heat

CONDITIONS TO AVOID: None

SECTION VI - TOXICOLOGICAL PROPERTIES SKIN CONTACT X SKIN ABSORPTION

ENTRY ROUTE TABLE EYE CONTACT X INHALATION ACUTE INHALATION CHRONIC

EFFECTS OF ACUTE EXPOSURE TO MATERIAL: Product may irritate eyes and skin. Ingestion causes vomiling, diarrhea, depressed respiration. EFFECTS OF CHRONIC EXPOSURE TO MATERIAL: Skin chapping.

LD50 (SPECIFY SPECIES & ROUTE):	LC50 (SPECIFY SPECIES):	EXPOSURE LIMIT:	IRRITANCY:
Not available	Not available	Not Available	Eye and skin.
SENSITIZING CAPACITY:	CARCINOGENICITY:	REPRODUCTIVITY EFFECTS:	SYNERGISTIC MATERIALS:
None known	None	None known	None known

SECTION VII - PREVENTATIVE MEASURES

RESPIRATORY PROTECTION (SPECIFY TYPE): Not required under normal conditions of use.

VENTILATION: General dilution ventilation.

PROTECTIVE GLOVES: Rubber gloves should be worn. EYE PROTECTION: Goggles / glasses with side shields

OTHER PROTECTIVE EQUIPMENT: None required.

SPILL PROCEDURES: Mechanically collect. Wash area with water. Prevent from entering sewers or waterways. Spilled material may cause slippery conditions. Promptly report significant spills to appropriate authorities. Consult local regulations.

WASTE DISPOSAL METHOD: Destroy by incineration at an approved facility. Dried material only may be landfilled. Consult local regulations.

STORAGE & HANDLING PRECAUTIONS: Store in ventilated area as close to 70°F as possible.

OTHER PRECAUTIONS: Keep containers closed when not in use. Keep out of reach of children.

SECTION VIII - FIRST AID MEASURES

EYES: Flush with water for 20 minutes holding eyelids open. Obtain medical attention immediately. SKIN: Wash with soap and water. Remove dried adhesive with mineral spirits followed by soap and water. Remove contaminated clothing and launder before re-use. Consult physician if irritation develops.

INGESTION: Do not induce vomiting. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration. Contact physician immediately.